

DIAGNOSTIC CENTER

Fayetteville, NC

This Fayetteville Diagnostic Center consisted of a 12,000 square foot interior fit-up for a new diagnostic facility. The facility included offices for administration and operating staff as well as the following:

- an open MRI
- a closed MRI
- a CT Scanner
- three (3) X-rays
- three (3) Mammography
- three (3) Ultra-sound
- two (2) Dark Rooms



The work included structural modifications for the installed MRI's and a future MRI that required magnetic shielding, custom casework, metal stud framing and drywall, lead-lined walls, ceramic tile, carpeting, wall coverings, acoustical ceilings, painting, RF shielding, plumbing, HVAC and electrical.

Owner: HealthSouth Medical Services

Architect: Gould Turner

